

---

## Errata

- Clearing Lockbits at High  $V_{CC}$  or temperature
- Wrong Clearing of XTRF in MCUSR
- Reset During EEPROM Write
- Verifying EEPROM in System
- Serial Programming at Voltages below 3.0 Volts
- High  $I_{CC}$  in Power Down with External Clock Running
- Wrong Latching of RCEN Fuse

### 7. Clearing Lockbits at High $V_{CC}$ or Temperature

If the temperature is too high, and/or the programming voltage is too high, the clearing of lockbits might fail.

#### Problem Fix/Workaround

Keep  $V_{CC}$  below 5.0 volts at room temperature when performing a chip erase.

### 6. Wrong Clearing of XTRF in MCUSR

The XTRF flag in MCUSR will be cleared when clearing the PORF flag. The flag does not get cleared by writing a "0" to it.

#### Problem Fix/Workaround

Finish the test of both flags before clearing any of them. Clear both flags simultaneously by writing 0 to both PORF and XTRF in MCUCR.

### 5. Reset During EEPROM Write

If reset is activated during EEPROM write the result is not what should be expected. The EEPROM write cycle completes as normal, but the address registers are reset to 0. The result is that both the address written and address 0 in the EEPROM can be corrupted.

#### Problem Fix/Workaround

Avoid using address 0 for storage, unless you can guarantee that you will not get a reset during EEPROM write.

### 4. Verifying EEPROM in System

EEPROM verify in In-System Programming mode cannot operate with maximum clock frequency. This is independent of the SPI clock frequency.

#### Problem Fix/Workaround

Reduce the clock speed, or avoid using the EEPROM verify feature.

### 3. Serial Programming at Voltages below 3.0 Volts

At voltages below 3.0 volts, serial programming might fail.

#### Problem Fix/Workaround

Keep  $V_{CC}$  at 3.0 volts or higher during in-system programming.

### 2. High $I_{CC}$ in Power Down with External Clock Running

When the external clock is running while the device is in power down, the power consumption will be higher than specified.

#### Problem Fix/Workaround

Stop the external clock while the device is in power down.



---

## 8-bit AVR<sup>®</sup> Microcontroller with 2K bytes of In-System Programmable Flash

---

## AT90S/LS2343 Rev. F Errata Sheet

Rev. 1193C-02/00



### 1. Wrong Latching of RCEN fuse

If  $V_{CC}$  goes below GND and then up to the operating voltage, the RCEN fuse can be read as unprogrammed even if it is programmed. The result of this is that the device starts looking for a clock signal on the external clock input instead of from the internal RC oscillator, making it look as if it “hangs”.

### Problem Fix/Workaround

If internal oscillator is required, use the 100% pin and code compatible ATtiny22L which has internal RC option only.



## Atmel Headquarters

### *Corporate Headquarters*

2325 Orchard Parkway  
San Jose, CA 95131  
TEL (408) 441-0311  
FAX (408) 487-2600

### *Europe*

Atmel U.K., Ltd.  
Coliseum Business Centre  
Riverside Way  
Camberley, Surrey GU15 3YL  
England  
TEL (44) 1276-686-677  
FAX (44) 1276-686-697

### *Asia*

Atmel Asia, Ltd.  
Room 1219  
Chinachem Golden Plaza  
77 Mody Road Tsimhatsui  
East Kowloon  
Hong Kong  
TEL (852) 2721-9778  
FAX (852) 2722-1369

### *Japan*

Atmel Japan K.K.  
9F, Tonetsu Shinkawa Bldg.  
1-24-8 Shinkawa  
Chuo-ku, Tokyo 104-0033  
Japan  
TEL (81) 3-3523-3551  
FAX (81) 3-3523-7581

## Atmel Operations

### *Atmel Colorado Springs*

1150 E. Cheyenne Mtn. Blvd.  
Colorado Springs, CO 80906  
TEL (719) 576-3300  
FAX (719) 540-1759

### *Atmel Rousset*

Zone Industrielle  
13106 Rousset Cedex  
France  
TEL (33) 4-4253-6000  
FAX (33) 4-4253-6001

---

### *Fax-on-Demand*

North America:  
1-(800) 292-8635  
International:  
1-(408) 441-0732

### *e-mail*

[literature@atmel.com](mailto:literature@atmel.com)

### *Web Site*

<http://www.atmel.com>

### *BBS*

1-(408) 436-4309

### © Atmel Corporation 2000.

Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

Marks bearing ® and/or ™ are registered trademarks and trademarks of Atmel Corporation.

Terms and product names in this document may be trademarks of others.



Printed on recycled paper.

1193C-02/00/xM