Errata

- Clearing Lockbits at High V_{CC} or Temperature
- Wrong Clearing of XTRF in MCUSR
- Reset During EEPROM Write
- Verifying EEPROM in System
- Serial Programming at Voltages below 3.0 Volts
- Missing External Clock Option

6. Clearing Lockbits at High V_{CC} or Temperature

If the temperature is too high, and/or the programming voltage is too high, the clearing of lockbits might fail.

Problem Fix/Workaround

Keep V_{CC} below 5.0 volts at room temperature when performing a chip erase.

5. Wrong Clearing of XTRF in MCUSR

The XTRF flag in MCUSR will be cleared when clearing the PORF flag. The flag does not get cleared by writing a "0" to it.

Problem Fix/Workaround

Finish the test of both flags before clearing any of them. Clear both flags simultaneously by writing 0 to both PORF and XTRF in MCUSR.

4. Reset During EEPROM Write

If reset is activated during EEPROM write the result is not what should be expected. The EEPROM write cycle completes as normal, but the address registers are reset to 0. The result is that both the address written and address 0 in the EEPROM can be corrupted.

Problem Fix/Workaround

Avoid using address 0 for storage, unless you can guarantee that you will not get a reset during EEPROM write.

3. Verifying EEPROM in System

EEPROM verify in In-System Programming mode cannot operate with maximum clock frequency. This is independent of the SPI clock frequency.

Problem Fix/Workaround

Reduce the clock speed, or avoid using the EEPROM verify feature.

2. Serial Programming at Voltages below 3.0 Volts

At voltages below 3.0 volts, serial programming might fail.

Problem Fix/Workaround

Keep V_{CC} at 3.0 volts or higher during in-system programming.

1. Missing external clock option

Early revisions of the ATtiny22L datasheet showed an external clock option and two different speed grades. This information was incorrect as ATtiny22L has internal oscillator only.

Problem Fix/Workaround

If external oscillator is required, use the 100% pin- and code-compatible AT90S/LS2343 which has external clock option only.



8-bit **AVR**® Microcontroller with 2K bytes of In-System Programmable Flash

ATtiny22L Rev. G Errata Sheet







Atmel Headquarters

Corporate Headquarters 2325 Orchard Parkway San Jose, CA 95131 TEL (408) 441-0311 FAX (408) 487-2600

Europe

Atmel U.K., Ltd.
Coliseum Business Centre
Riverside Way
Camberley, Surrey GU15 3YL
England
TEL (44) 1276-686-677
FAX (44) 1276-686-697

Asia

Atmel Asia, Ltd.
Room 1219
Chinachem Golden Plaza
77 Mody Road Tsimhatsui
East Kowloon
Hong Kong
TEL (852) 2721-9778
FAX (852) 2722-1369

Japan

Atmel Japan K.K. 9F, Tonetsu Shinkawa Bldg. 1-24-8 Shinkawa Chuo-ku, Tokyo 104-0033 Japan TEL (81) 3-3523-3551 FAX (81) 3-3523-7581

Atmel Operations

Atmel Colorado Springs 1150 E. Cheyenne Mtn. Blvd. Colorado Springs, CO 80906 TEL (719) 576-3300 FAX (719) 540-1759

Atmel Rousset
Zone Industrielle
13106 Rousset Cedex
France
TEL (33) 4-4253-6000
FAX (33) 4-4253-6001

Fax-on-Demand North America: 1-(800) 292-8635 International: 1-(408) 441-0732

e-mail literature@atmel.com

Web Site http://www.atmel.com

BBS 1-(408) 436-4309

© Atmel Corporation 2000.

Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

Marks bearing $^{\text{@}}$ and/or $^{\text{\tiny{TM}}}$ are registered trademarks and trademarks of Atmel Corporation.

Printed on recycled paper.